

MOTORSPORT SUIT

Thank you for choosing Racer Ink...

In order to preserve the quality of your clothing we recommend you read this manual carefully and to keep your garments in a safe place.

For further information about this and other products please contact Racer ink's customer service department.

Operation and maintenance of the suit – (Guaranteed)

In order to maintain lasting longevity of the fabrics technical characteristics, it is recommended you wash the garment in accordance with the instructions outlined below.

Always dry the garment before being placed in a closed bag or closed spaces in order to avoid damage to materials or finishes (printing or fabric etc). Leave the suit in the open air and out of direct sunlight. Best if washed soon after every use.

Avoid washing process at temperatures higher than those recommended.

Do not use aggressive products (i.e. bleach, oxygen active products) that may damage the fabrics, components, embroidery and printed applications.

Ensure all Velcro and the zippers are closed to avoid damage during the washing machine cycle.

Avoid automatic drying processes.

Any damage to the garment caused by improper maintenance will invalidate any warranty on the product.

Use the bag supplied when transporting the suit to avoid contact with solvents or other chemicals that may damage the fabrics.

It is recommended to:

- Machine wash at 30 degrees Celsius
- The use of a colour capture sheet

It is recommended that the following are not used :

- Any type of bleach or chlorine
- Brighteners or whiteners
- Disinfectants
- Softeners
- Bleach hydrogen peroxide

CARE INSTRUCTIONS

Important:

The garment should not be left damp for long periods. After a brief spin cycle it should hung inside out, avoiding as much as possible prolonged exposure to light, especially sun rays. Let garment dry in the shade.

Always make sure to not put away garments unless they are completely dry to eliminate the possibility of creating mold.

Please ensure you don't leave a damp suit in a bag.

Following these instructions will prolong the life of the suit and its colors.



Max temp 30 degrees Celsius, reduced mechanical action, normal rinse, normal spin, do not wring dry.



Do not iron



Do not bleach



Do not dry clean



Do not tumble dry



Hang dry, after removing excess water (spin cycle)



Dry in the shade. This symbol is placed next to the hanging or flat drying symbols to indicate that the drying process is to take place away from direct sunlight.

Racer Ink is not responsible for damage sustained from improper use, abuse or incorrect maintenance. The company also will evaluate the conditions given to the clothing for repair or change.